

DATE : 27-May-2018

River	Station	Gauging Station				Water Level before 1hr	Water Level at 03.00 pm	Remarks	Water Level Rising or Falling	RF in last 6 hrs mm
		Coordinate	Catchment Area (km ²)	Unit	Alert Level					
Kelsari Ganga (RB 01)	N' Street	6° 57' 35" N 79° 52' 36.6" E	2085	ft	4.00	5.00	7.00	Normal		0.2
	Hanwella	6° 54' 39.38" N 80° 05' 3.16" E	1782	m	7.00	8.00	10.00	Normal		0.0
	Glencourse	6° 58' 25" N 80° 11' 3" E	1463	m	15.00	16.50	19.90	Normal		1.7
Kalu-Ganga (RB 03)	Holombuwa	7° 11' 6.6" N 80° 15' 53.3" E	155	m	3.00	3.40	5.00	Normal		0.5
	Deraniyagala	8° 55' 23.23" N 80° 20' 20.3" E	183	m	4.80	5.80	6.40	Normal		0.0
	Kitulgala	6° 59' 25" N 80° 24' 50" E	383	m	2.00	3.00	5.00	Normal		0.0
Gin Ganga (RB 09)	Norwood	6° 50' 8.32" N 80° 36' 52.75" E	97	m	1.50	2.00	2.15	Normal		0.0
	Ratnapura	6° 40' 43.2" N 80° 23' 49.8" E	603	m	5.20	7.50	9.50	Normal		0.0
	Ellagawa	6° 43' 54" N 80° 13' 4.2" E	1393	m	10.00	10.70	12.20	Normal		0.0
Nilwata Ganga (RB 12)	Milakanda	6° 37' 50.3" N 80° 9' 37.7" E	780	m	5.00	6.50	8.00	Flood	Falling	0.0
	Putupaula	6° 36' 51.9" N 80° 3' 44.2" E	2598	m	3.00	4.00	5.00	Alert	Falling	0.0
	Tawalama	8° 20' 33.3" N 80° 19' 55.2" E	377	m	4.25	4.50	6.10	Normal		2.5
Maha Oya (RB 102)	Baddegama	6° 10' 25" N 80° 10' 33.1" E	749	m	3.50	4.00	5.00	Normal		0.0
	Pitabeddara	6° 12' 48.2" N 80° 28' 34.5" E	310	m	3.25	4.00	5.00	Normal		4.2
	Panadugama	6° 08' 00" N 80° 29' 00" E	445	m	5.00	6.00	6.50	Normal		6.0
Attanagalu Oya (RB 103)	Urawa	6° 44' 11.8" N 80° 34' 18" E	59	m	2.50	3.00	4.00	Normal		5.6
	Badatgama	7° 18' 3.3" N 79° 58' 50" E	1360	ft	1.00	5.00	16.00	Normal		6.0
	Giriulla	7° 19' 30" N 80° 6' 53.3" E	1192	m	5.00	6.00	6.50	Normal		2.0
Attanagalu Oya (RB 103)	Dunamate	7° 7' 0" N 80° 4' 54.5" E	153	m	3.30	4.40	5.50	Flood	Falling	4.8

RECEIVED
EMERGENCY OPERATIONS DIVISION
Date : 2018/05/27
Time : 15:40 hrs
D (Ops)/DO/ADO

G.A.S.A. Jayamal
W-1 J. Abeysiripala

Prepared by
Checked by

Eng.R.M.M.R. Alawathugoda
Director (Hydrology)