

Islandwide Water Level Situation in Major Rivers

DATE : 22-Sep-2019

TIME : 3:30 PM

River	Gauging Station							Water Level before 1hr	Water Level at 03:00 PM	Remarks	Water Level Rising or Falling	Rainfall in Last 6 hrs
	Station	Coordinate	Catchment Area (km ²)	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kalu Ganga (RB 03)	Ratnapura	6° 40' 43.2" N 80° 23' 49.8" E	603	m	5.20	7.50	9.50	1.69	1.69	Normal		0.0
	Ellagawa	6° 43' 54" N 80° 13' 4.2" E	1393	m	10.00	10.70	12.20	6.02	6.02	Normal		0.0
	Millakanda	6° 37' 50.3" N 80° 9' 37.7" E	780	m	5.00	6.50	8.00	5.14	5.16	Alert	Rising	0.0
	Putupaula	6° 36' 51.9" N 80° 3' 44.2" E	2598	m	3.00	4.00	5.00	1.48	1.48	Normal		0.0
Gin Ganga (RB 09)	Tawalama	6° 20' 33.3" N 80° 19' 55.2" E	377	m	4.00	4.50	6.10	3.89	3.73	Normal		0.0
	Baddegama	6° 10' 25" N 80° 10' 33.1" E	749	m	3.50	4.00	5.00	3.33	3.37	Normal		4.1
Nilwala Ganga (RB 12)	Pitabeddara	6° 12' 48.2" N 80° 28' 34.5" E	310	m	3.25	4.00	5.00	3.75	3.65	Alert	Falling	0.0
	Panadugama	6° 08' 00" N 80° 29' 00" E	445	m	5.00	6.00	6.50	6.62	6.64	Major Flood	Rising	3.5
	Urawa	6° 14' 11.8" N 80° 34' 18" E	59	m	2.50	3.00	4.00	2.59	2.21	Normal		0.0

Prepared by :
Checked by :

H.P.S.W.Gunawardhana
Shayani Saumya

Handwritten notes:
 @me - b...
 22/09/2019
 Date 2019-09-22
 Time 15:48

EMERGENCY OPERATIONS DIVISION
RECEIVED
 Date 2019-09-22
 Time 15:48
 D (007/00140)
DISASTER MANAGEMENT CENTRE

Eng.R.M.M.R.Alawathugoda
Director (Hydrology)

Eng. R. M. M. R. Alawathugoda
Director of Irrigation Hydrology
Hydrology Division
Irrigation Department
Colombo 07.

for :

 (H.A.)