

### Islandwide Water Level Situation in Major Rivers

DATE : 18-Jul-2019

TIME : 04.30 PM

River	Gauging Station							Water Level before 1hr	Water Level at 4.00 pm	Remarks	Water Level Rising or Falling	Last 3 hr Rainfall mm
	Station	Coordinate	Catchment Area (km <sup>2</sup> )	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	N' Street	6° 57' 35" N 79° 52' 36.6" E	2085	ft	4.00	5.00	7.00	2.95	2.70	Normal		-
	Hanwella	6° 54' 39.38" N 80° 05' 3.16" E	1782	m	7.00	8.00	10.00	1.68	1.79	Normal		-
	Glencourse	6° 58' 25" N 80° 11' 3" E	1463	m	15.00	16.50	19.00	10.40	10.48	Normal		0.3
	Holombuwa	7° 11' 6.6" N 80° 15' 53.3" E	155	m	3.00	3.40	5.00	0.47	0.49	Normal		0.3
	Deraniyagala	6° 55' 23.23" N 80° 20' 20.3" E	183	m	4.80	5.80	6.40	3.35	3.53	Normal		3.7
	Kitulgala	6° 59' 25" N 80° 24' 50" E	383	m	3.00	4.00	6.00	3.31	3.53	Alert	Rising	10.8
	Norwood	6° 50' 8.32" N 80° 36' 52.75" E	97	m	1.50	2.00	2.15	1.49	1.67	Alert	Rising	31.6
Kalu Ganga (RB 03)	Ratnapura	6° 40' 43.2" N 80° 23' 49.8" E	603	m	5.20	7.50	9.50	6.20	7.00	Alert	Rising	21.8
	Ellagawa	6° 43' 54" N 80° 13' 4.2" E	1393	m	10.00	10.70	12.20	5.80	6.05	Normal		3.4
	Millakanda	6° 37' 50.3" N 80° 9' 37.7" E	780	m	5.00	6.50	8.00	3.30	3.56	Normal		1.1
	Putupaula	6° 36' 51.9" N 80° 3' 44.2" E	2598	m	3.00	4.00	5.00	0.91	1.01	Normal		-

Prepared by :  
Checked by :P.A.G.Gayampath  
D.A.Somawickrama

EMERGENCY OPERATIONS DIVISION


RECEIVED

Date : 07/19

Time : 1643

  
 D (Ops)/DO/ADO

DISASTER MANAGEMENT CENTRE

  
 Eng. R.M.M.R. Alawathugoda  
 Director (Hydrology)

 Eng. R. M. M. R. Alawathugoda  
 Director of Irrigation (Hydrology)  
 Hydrology Division  
 Irrigation Department  
 Colombo 07.