

Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 15-May-2023


TIME : 6:30 AM

| River Basin | Tributory/River | Gauging Station | | | | | Water Level at 05:00 am | Water Level at 06:00 am | Remarks | Water Level Rising or Falling | 21 Hr RF in mm at 06:00 am |
|-----------------------|-----------------|--------------------------|------|-------------|-------------------|-------------------|-------------------------|-------------------------|-------------|-------------------------------|----------------------------|
| | | Station | Unit | Alert Level | Minor Flood Level | Major Flood Level | | | | | |
| Kalu Ganga (RB 03) | Kalu Ganga | Ellagawa | m | 10.00 | 10.70 | 12.20 | 7.13 | 7.10 | Normal | | 23.9 |
| | Kalu Ganga | Ratnapura | m | 5.20 | 7.50 | 9.50 | 2.99 | 2.89 | Normal | | 4.5 |
| | Maguru Ganga | Magura | m | 4.00 | 6.00 | 7.50 | 4.66 | 4.60 | Alert | Falling | 23.3 |
| | Kuda Ganga | Kalawellawa (Millakanda) | m | 5.00 | 6.50 | 8.00 | 5.76 | 5.78 | Alert | Rising | 25.2 |
| Gin Ganga (RB 09) | Gin Ganga | Tawalama | m | 4.00 | 6.00 | 7.50 | 6.41 | 6.29 | Minor Flood | Falling | 107.0 |
| | Gin Ganga | Baddegama | m | 3.50 | 4.00 | 5.00 | 3.95 | 3.96 | Alert | Rising | 13.1 |
| Nilwala Ganga (RB 12) | Nilwala Ganga | Thalgahagoda | m | 1.40 | 1.70 | 2.80 | 1.74 | 1.74 | Minor Flood | | 37.2 |
| | Nilwala Ganga | Panadugama | m | 5.00 | 6.00 | 7.50 | 7.44 | 7.45 | Minor Flood | Rising | 62.7 |
| | Nilwala Ganga | Pitabeddara | m | 4.00 | 5.00 | 6.50 | 5.80 | 5.39 | Minor Flood | Falling | 276.8 |
| | Urubokka Ganga | Urawa | m | 2.50 | 4.00 | 6.00 | 1.75 | 0.90 | Normal | | 184.7 |

Prepared by : K.G.D.C.Dissanayake (H.A.)

Checked by : G.A.S.A.Jayamal (H.A.)

Eng. S.P.C. Sugeeshwara
 Director of Irrigation
 (Hydrology & Disaster Management)
 Irrigation Department
 230, Baudhaloka Mawatha,
 Colombo - 07



Eng.S.P.C.Sugeeshwara
 Director (Hydrology and Disaster Management)