

Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 3-Jun-2023


TIME : 6:30 AM

River Basin	Tributary/River	Gauging Station					Water Level at 05:00 am	Water Level at 06.00 am	Remarks	Water Level Rising or Falling	21 Hr RF in mm at 06:00 am
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	2.4	2.4	Normal		0.0
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	8.58	8.58	Normal		3.6
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	3.38	3.30	Normal		0.0
	Maguru Ganga	Magura	m	4.00	6.00	7.50	4.70	4.72	Alert	Rising	0.0
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	6.72	6.76	Minor Flood	Rising	5.9
Gin Ganga (RB 09)	Gin Ganga	Tawalama	m	4.00	6.00	7.50	2.52	2.47	Normal		5.3
	Gin Ganga	Baddegama	m	3.50	4.00	5.00	3.89	3.92	Alert	Rising	1.1
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.52	1.51	Alert	Falling	22.7
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	5.52	5.50	Alert	Falling	3.3
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	1.69	1.51	Normal		0.0
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	0.50	0.48	Normal		0.0

Prepared by : K.K.C.U.Dilshan (H.A.)

Checked by : W.H.J.Abeywickrama(H.D.S.)

Eng. S.P.C. Sugeeshwara
 Director of Irrigation
 (Hydrology & Disaster Management)
 Irrigation Department
 230, Baudhaloka Mawatha,
 Colombo - 07



Eng.S.P.C.Sugeeshwara
 Director (Hydrology and Disaster Management)