



Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 6-Nov-2023

TIME : 6:30 PM

River Basin	Tributary/River	Gauging Station					Water Level at 5:00 pm	Water Level at 6:00 pm	Remarks	Water Level Rising or Falling	9 Hr RF in mm at 6.00 pm
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	Kelani Ganga	N' Street	ft	4.00	5.00	7.00	2.70	2.70	Normal		-
	Kelani Ganga	Hanwella	m	7.00	8.00	10.00	4.78	4.88	Normal		59.0
	Kelani Ganga	Glencourse	m	15.00	16.50	19.00	12.21	12.38	Normal		55.3
	Kelani Ganga	Kitulgala	m	3.00	4.00	6.00	2.26	2.33	Normal		41.3
	Gurugoda Oya	Holombuwa	m	3.00	3.40	5.00	1.19	1.37	Normal		6.7
	Seethawaka Ganga	Deraniyagala	m	4.80	5.80	6.40	0.97	1.14	Normal		25.9
	Kehelgamu Oya	Norwood	m	1.50	3.00	4.50	1.35	1.33	Normal		16.8
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	1.88	1.91	Normal		14.8
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	7.83	7.88	Normal		21.3
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	3.61	3.60	Normal		32.4
	Maguru Ganga	Magura	m	4.00	6.00	7.50	2.45	2.40	Normal		2.1
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	4.91	5.00	Alert	Rising	56.6
Gin Ganga (RB 09)	Gin Ganga	Baddegama	m	3.50	4.00	5.00	3.20	3.21	Normal		10.8
	Gin Ganga	Tawalama	m	4.00	6.00	7.50	2.40	2.44	Normal		1.6
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.89	1.90	Minor Flood	Rising	1.2
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	5.96	6.35	Minor Flood	Rising	23.8
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	3.20	3.51	Normal		39.3
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	1.31	1.31	Normal		0.0
Walawe Ganga (RB 18)	Walawe Ganga	Moraketiya	m	1.80	3.50	5.00	3.60	3.59	Minor Flood	Falling	0.7
Yan Oya (RB 67)	Yan Oya	Horowpatana	m	6.00	7.50	10.50	7.25	7.25	Alert		39.6
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	m	5.00	6.80	7.80	3.85	3.76	Normal		10.9
Deduru Oya (RB 99)	Deduru Oya	Moragaswewa	m	4.75	6.00	7.00	6.15	6.15	Minor Flood		14.1
Maha Oya (RB 102)	Maha Oya	Badalgama	m	5.00	6.20	9.60	4.16	4.10	Normal		41.5
	Maha Oya	Giriulla	m	5.50	6.50	7.50	2.85	2.78	Normal		9.2
Attanagalu Oya (RB 103)	Attanagalu Oya	Dunamale	m	3.30	4.40	5.50	4.98	4.98	Minor Flood		27.8

Prepared by : K.K.C.U.Dilshan (H.A.)
 Checked by : G.A.S.A.Jayamal (H.A.)

Eng. S.P.C. Sugeeshwara
 Director of Irrigation
 (Hydrology & Disaster Management)
 Irrigation Department
 230, Bauddhaloka Mawatha,
 Colombo - 07

Eng.S.P.C.Sugeeshwara
 Director (Hydrology and Disaster Management)