



වාරිමාර්ග දෙපාර්තමේන්තුව  
நீர்ப்பாசனத் திணைக்களம்  
**IRRIGATION DEPARTMENT**  
(ජලවිද්‍යා හා ආපදා කළමනාකරණ අංශය)



**Islandwide Water Level & Rainfall Situation in Major Rivers**

DATE : 9-Nov-2023

TIME : 3:30 PM

River Basin	Tributary/River	Gauging Station					Water Level at 2:00 pm	Water Level at 3:00 pm	Remarks	Water Level Rising or Falling	6 Hr RF in mm at 3.00 p.m.
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	Kelani Ganga	N' Street	ft	4.00	5.00	7.00	2.95	2.70	Normal		-
	Kelani Ganga	Hanwella	m	7.00	8.00	10.00	4.75	4.66	Normal		0.0
	Kelani Ganga	Glencourse	m	15.00	16.50	19.00	11.60	11.55	Normal		0.0
	Kelani Ganga	Kitulgala	m	3.00	4.00	6.00	2.00	2.10	Normal		0.5
	Gurugoda Oya	Holombuwa	m	3.00	3.40	5.00	1.36	1.34	Normal		0.0
	Seethawaka Ganga	Deraniyagala	m	4.80	5.80	6.40	0.88	0.89	Normal		0.0
	Kehelgamu Oya	Norwood	m	1.50	3.00	4.50	1.15	1.21	Normal		1.0
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	2.19	2.16	Normal		0.0
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	7.00	6.98	Normal		0.0
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	2.82	2.75	Normal		0.0
	Maguru Ganga	Magura	m	4.00	6.00	7.50	3.14	3.08	Normal		9.7
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	5.92	5.90	Alert	Falling	0.0
Gin Ganga (RB 09)	Gin Ganga	Baddegama	m	3.50	4.00	5.00	2.77	2.75	Normal		0.0
	Gin Ganga	Tawalama	m	4.00	6.00	7.50	2.30	2.27	Normal		0.0
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.89	1.88	Minor Flood	Falling	0.0
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	5.57	5.56	Alert	Falling	0.0
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	1.83	1.90	Normal		28.6
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	1.17	2.02	Normal		17.2
Walawe Ganga (RB 18)	Walawe Ganga	Moraketiya	m	1.80	3.50	5.00	2.70	2.70	Alert		4.9
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	m	5.00	6.80	7.80	1.82	1.82	Normal		24.6
Deduru Oya (RB 99)	Deduru Oya	Moragaswewa	m	4.75	6.00	7.00	3.86	3.60	Normal		0.0
Maha Oya (RB 102)	Maha Oya	Badalgama	m	5.00	6.20	9.60	4.31	4.22	Normal		0.0
	Maha Oya	Giriulla	m	5.50	6.50	7.50	3.08	3.03	Normal		0.0
Attanagalu Oya (RB 103)	Attanagalu Oya	Dunamale	m	3.30	4.40	5.50	4.96	4.93	Minor Flood	Falling	0.0

Prepared by : P.A.G.Gayampath (H.A.)  
Checked by : W.A.S.Saumya (H.D.S.(Act))

Eng. S.P.C. Sugeeshwara  
Director of Irrigation  
(Hydrology & Disaster Management)  
Irrigation Department  
230, Bauddhaloka Mawatha,  
Colombo - 07

Eng.S.P.C.Sugeeshwara  
Director (Hydrology and Disaster Management)