



වාරිමාර්ග දෙපාර්තමේන්තුව
நீர்ப்பாசனத் திணைக்களம்
IRRIGATION DEPARTMENT
 (ජලවිද්‍යා හා ආපදා කළමනාකරණ අංශය)



Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 9-Nov-2023

TIME : 6:30 PM

River Basin	Tributary/River	Gauging Station					Water Level at 5:00 pm	Water Level at 6:00 pm	Remarks	Water Level Rising or Falling	9 Hr RF in mm at 6.00 p.m.
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	Kelani Ganga	N' Street	ft	4.00	5.00	7.00	2.50	2.50	Normal		-
	Kelani Ganga	Hanwella	m	7.00	8.00	10.00	4.52	4.54	Normal		49.5
	Kelani Ganga	Glencourse	m	15.00	16.50	19.00	11.96	12.30	Normal		51.6
	Kelani Ganga	Kitulgala	m	3.00	4.00	6.00	2.10	2.25	Normal		6.8
	Gurugoda Oya	Holombuwa	m	3.00	3.40	5.00	1.59	2.46	Normal		50.1
	Seethawaka Ganga	Deraniyagala	m	4.80	5.80	6.40	1.03	1.38	Normal		47.7
	Kehelgamu Oya	Norwood	m	1.50	3.00	4.50	1.70	2.05	Alert	Rising	58.3
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	2.09	2.06	Normal		0.7
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	7.04	7.40	Normal		83.5
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	2.77	3.03	Normal		12.3
	Maguru Ganga	Magura	m	4.00	6.00	7.50	2.98	2.70	Normal		11.0
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	5.85	5.87	Alert	Rising	8.3
Gin Ganga (RB 09)	Gin Ganga	Baddegama	m	3.50	4.00	5.00	2.72	2.70	Normal		0.0
	Gin Ganga	Tawalama	m	4.00	6.00	7.50	2.43	2.71	Normal		38.4
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.88	1.88	Minor Flood		1.8
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	5.57	5.59	Alert	Rising	6.4
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	1.85	2.00	Normal		32.6
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	2.56	2.45	Normal		22.3
Walawe Ganga (RB 18)	Walawe Ganga	Moraketiya	m	1.80	3.50	5.00	2.82	2.86	Alert	Rising	4.9
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	m	5.00	6.80	7.80	1.91	1.99	Normal		24.6
Deduru Oya (RB 99)	Deduru Oya	Moragaswewa	m	4.75	6.00	7.00	3.42	3.30	Normal		0.5
Maha Oya (RB 102)	Maha Oya	Badalgama	m	5.00	6.20	9.60	4.10	4.04	Normal		2.2
	Maha Oya	Giriulla	m	5.50	6.50	7.50	2.95	3.17	Normal		49.3
Attanagalu Oya (RB 103)	Attanagalu Oya	Dunamale	m	3.30	4.40	5.50	4.88	4.88	Minor Flood		25.0

Prepared by : K.K.C.U.Dilshan (H.A.)
 Checked by : P.A.G.Gayampath (H.A.)

Eng. S.P.C. Sugeeshwara
 Director of Irrigation
 (Hydrology & Disaster Management)
 Irrigation Department
 230, Bauddhaloka Mawatha,
 Colombo - 07

Eng.S.P.C.Sugeeshwara
 Director (Hydrology and Disaster Management)