



වාරිමාර්ග දෙපාර්තමේන්තුව
நீர்ப்பாசனத் திணைக்களம்
IRRIGATION DEPARTMENT
 (ජලවිද්‍යා හා ආපදා කළමනාකරණ අංශය)



Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 20-Dec-2023

TIME : 3:30 PM

River Basin	Tributary/River	Gauging Station					Water Level at 2:00 pm	Water Level at 3:00 p.m	Remarks	Water Level Rising or Falling	6 Hr RF in mm at 3.00 p.m
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	Kelani Ganga	N' Street	ft	4.00	5.00	7.00	1.00	1.10	Normal		-
	Kelani Ganga	Hanwella	m	7.00	8.00	10.00	2.46	2.41	Normal		0.3
	Kelani Ganga	Glencourse	m	15.00	16.50	19.00	10.20	10.20	Normal		0.0
	Kelani Ganga	Kitulgala	m	3.00	4.00	6.00	1.88	1.88	Normal		3.6
	Gurugoda Oya	Holombuwa	m	3.00	3.40	5.00	0.96	0.94	Normal		0.0
	Seethawaka Ganga	Deraniyagala	m	4.80	5.80	6.40	0.70	0.73	Normal		13.7
	Kehegamu Oya	Norwood	m	1.50	3.00	4.50	0.99	0.97	Normal		0.0
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	1.87	1.81	Normal		3.5
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	6.85	6.78	Normal		0.0
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	2.42	2.39	Normal		4.2
	Maguru Ganga	Magura	m	4.00	6.00	7.50	2.36	2.29	Normal		0.0
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	5.17	5.12	Alert	Falling	4.9
Gin Ganga (RB 09)	Gin Ganga	Baddegama	m	3.50	4.00	5.00	3.51	3.45	Normal		0.0
	Gin Ganga	Tawalama	m	4.00	6.00	7.50	2.23	2.22	Normal		0.0
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.96	1.96	Minor Flood		2.3
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	5.60	5.58	Alert	Falling	5.8
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	1.54	1.54	Normal		0.5
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	0.98	0.98	Normal		2.6
Walawe Ganga (RB 18)	Walawe Ganga	Moraketiya	m	3.00	5.00	7.00	2.15	2.15	Normal		4.6
Yan Oya (RB 67)	Yan Oya	Horowpatana	m	6.00	7.50	10.50	4.22	4.16	Normal		0.0
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	m	5.00	6.80	7.80	6.38	6.30	Alert	Falling	0.0
Maha Oya (RB 102)	Maha Oya	Badalgama	m	5.00	6.20	9.60	3.01	3.00	Normal		0.0
	Maha Oya	Giriulla	m	5.50	6.50	7.50	1.80	1.78	Normal		2.0
Attanagalu Oya (RB 103)	Attanagalu Oya	Dunamale	m	3.30	4.40	5.50	3.44	3.36	Alert	Falling	0.0

Prepared by : K.K.C.U.Dilshan (H.A)
 Checked by : W.A.S.Saumya(H.D.S (Act))

Eng. S.P.C. Sugeeshwara
 Director of Irrigation
 (Hydrology & Disaster Management)
 Irrigation Department
 230, Baudhaloka Mawatha,
 Colombo - 07

Eng.S.P.C.Sugeeshwara
 Director (Hydrology and Disaster Management)