

Islandwide Water Level Situation in Major Rivers

DATE : 21-Dec-2019

TIME : 03.30 AM

River	Station	Coordinate	Catchment Area (km ²)	Gauging Station				Water Level before 1hr	Water Level at 03:00 a.m	Remarks	Water Level Rising or Falling	RF in last 18 hrs
				Unit	Alert Level	Minor Flood Level	Major Flood Level					
Maduru Oya (RB 54)	Padiyatalawa	7° 23' 0" N 81° 11' 30" E	159	m	4.00	4.50	6.00	2.33	2.15	Normal		57.9
	Nakkala	6° 53' 42.4" N 81° 17' 49.3" E	216	m	5.00	6.00	7.50	3.41	3.31	Normal		104.5
Heda Oya (RB 36)	Siyambalanduwa	6° 54' 16.5" N 81° 32' 44.4" E	295	m	4.50	5.00	5.60	5.43	4.51	Alert	Falling	41.2
	Weragantota	7° 19' 0" N 80° 59' 18.3" E	4092	m	5.00	6.00	8.00	2.58	2.31	Normal		56.9
Mahaweli Ganga (RB 60)	Manampitiya	7° 54' 53.3" N 81° 5' 10" E	7418	m	3.50	3.70	4.00	4.17	4.18	Major Flood	Rising	72.1
	Taldena	7° 5' 26.7" N 81° 2' 53.3" E	276	m	3.00	4.00	5.00	2.02	1.97	Normal		29.3
Mee Oya (RB 95)	Galgamuwa	7° 58' 13.3" N 80° 15' 18.3" E	299	m	4.84	5.94	7.00	6.69	6.68	Minor Flood	Falling	76.4

Prepared by : K.G.D.C.Dissanayake
Checked by : K.A.Amarasiri

Eng.R.M.M.R.Alawathugoda
Director (Hydrology)

