

Water Level Situation in Major Rivers

DATE : 22-Dec-2019

TIME : 6.30 A.M.

| River | Station | Coordinate | Gauging Station | | | | | Water Level before 1hr | Water Level at 6:00 am | Remarks | Water Level Rising or Falling |
|------------------------|-----------------------|--------------------------------|-----------------------------------|------|-------------|-------------------|-------------------|------------------------|------------------------|-------------|-------------------------------|
| | | | Catchment Area (km ²) | Unit | Alert Level | Minor Flood Level | Major Flood Level | | | | |
| Mee Oya (RB 95) | Galgamuwa | 7° 58' 13.3" N 80° 15' 18.3" E | 299 | m | 4.84 | 5.94 | 7.00 | 5.73 | 5.67 | Alert | Falling |
| Deduru Oya (RB 99) | Ridi bendi Ella (Dam) | 7° 43' 36" N 80° 15' 48" E | 1370 | m | | | | 1.74 | 1.72 | Normal | |
| Menik Ganga (26) | Katharagama | 6° 24' 56" N 81° 19' 51" E | 787 | m | 3.50 | 4.00 | 5.00 | 4.75 | 4.46 | Minor Flood | Falling |
| Mahaweli Ganga (RB 60) | Manampitiya | 7° 54' 53.3" N 81° 5' 10" E | 7418 | m | 3.50 | 3.70 | 4.00 | 2.77 | 2.69 | Normal | |

Prepared by :

K.A.Amarasiri

Eng.R.M.M.R.Alawathugoda
Director (Hydrology)

